

Photo#1:
View North over Location Center



Photo#2:
View South over Location Center



April 22, 2017

Photo#3:
View East over Location Center



Photo#4:
View West over Location Center



April 22, 2017

Photo#5:
View of Access Rd to North into Location



Photo#6:
View to South of Access Rd exiting Location



April 22, 2017

Photo#7:

View of Access Rd at take off point from County Rd.



April 22,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Matagorda Morgan Creek PA 081-07116

Photo#8:

Pile of Cinder block / Debris remaining on Location.



April 22,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Matagorda Morgan Creek PA 081-07116

Photo#9:

View of Reference area Vegetation..



April 22,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Matagorda Morgan Creek PA 081-07116