

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2017

Submitted Date:

04/27/2017

Document Number:

666803125

FIELD INSPECTION FORM

Loc ID 334901 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270069	WELL	PR	09/07/2004	GW	045-09447	SHIDELER 32-2D (G32NEC)	PR
270070	WELL	PR	04/01/2013	GW	045-09446	SHIDELER 32-8C (G32NEC)	PR

General Comment:

[Tank battery on location ID 334853](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Gas Meter Run	# 1			
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>
Plunger Lift	# 2			
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>
Vertical Heated Separator	# 2			
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No	NO		
Comment: <input type="text"/>			
Corrective Action: <input type="text"/>			Date: <input type="text"/>

Flaring:

Type			
Comment: <input type="text"/>			
Corrective Action: <input type="text"/>			Date: <input type="text"/>

Inspected Facilities

Facility ID: 270069 Type: WELL API Number: 045-09447 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 270070 Type: WELL API Number: 045-09446 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
Gravel	Pass					
Sediment Traps	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT