

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2017

Submitted Date:

04/27/2017

Document Number:

666803132**FIELD INSPECTION FORM**

Loc ID 311696 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289580	WELL	PR	05/20/2014	GW	045-13819	Dixon Fed CA B1	PR
289581	WELL	PR	08/01/2012	GW	045-13818	DIXON FED CA B2	PR
289582	WELL	PR	06/15/2011	GW	045-13817	DIXON FED CA B3	PR
289763	WELL	PR	08/01/2012	GW	045-13869	DIXON FED CA B7	PR
291432	WELL	PR	08/01/2012	GW	045-14373	Dixon Federal B10	PR
291433	WELL	PR	08/01/2012	GW	045-14372	DIXON FED CA B6	PR
291434	WELL	PR	01/17/2012	GW	045-14371	Dixon Federal B4	PR
291435	WELL	PR	01/17/2012	GW	045-14370	Dixon Federal B5	PR
291436	WELL	PR	01/17/2012	GW	045-14369	Dixon Federal B9	PR
291437	WELL	PR	09/15/2009	GW	045-14368	DIXON FEDERAL B8	PR
421653	WELL	PR	11/15/2011	GW	045-20424	DIXON FED CA B13	PR
421696	WELL	PR	12/20/2011	GW	045-20425	Dixon Federal B16	PR
421708	WELL	PR	04/20/2012	GW	045-20427	DIXON FED CA B14	PR
421709	WELL	PR	11/01/2012	GW	045-20428	Dixon Federal B11	PR
421710	WELL	PR	09/01/2012	GW	045-20429	Dixon Federal B15	PR
421716	WELL	PR	12/19/2011	GW	045-20432	Dixon Federal B12	PR

**General Comment:**[Inspection is for odor complaint in area](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 16

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 16

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,

Comment: [Centralized battery](#)

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.524269,-107.659405	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities						
Facility ID:	289580	Type:	WELL	API Number: 045-13819	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	289581	Type:	WELL	API Number: 045-13818	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	289582	Type:	WELL	API Number: 045-13817	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	289763	Type:	WELL	API Number: 045-13869	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291432	Type:	WELL	API Number: 045-14373	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291433	Type:	WELL	API Number: 045-14372	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291434	Type:	WELL	API Number: 045-14371	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	291435	Type:	WELL	API Number: 045-14370	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:

Facility ID:	291436	Type:	WELL	API Number:	045-14369	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	291437	Type:	WELL	API Number:	045-14368	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	421653	Type:	WELL	API Number:	045-20424	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	421696	Type:	WELL	API Number:	045-20425	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	421708	Type:	WELL	API Number:	045-20427	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	421709	Type:	WELL	API Number:	045-20428	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	421710	Type:	WELL	API Number:	045-20429	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	421716	Type:	WELL	API Number:	045-20432	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Ditches	Pass			
		Culverts	Pass			
Seeding	Pass					
Mulching	Pass					
		Gravel	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT