

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2017

Submitted Date:

04/27/2017

Document Number:

666803133**FIELD INSPECTION FORM**Loc ID 335538 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291065	WELL	PR	03/25/2010	GW	045-14284	VALLEY FARMS F2	PR
291066	WELL	PR	11/25/2009	GW	045-14285	VALLEY FARMS F3	PR
291067	WELL	PR	05/28/2008	GW	045-14286	VALLEY FARMS F5	PR
291072	WELL	PR	09/17/2013	GW	045-14289	VALLEY FARMS F7	PR
291073	WELL	PR	04/19/2010	GW	045-14290	VALLEY FARMS F1	PR
296414	WELL	PR	12/06/2009	GW	045-16011	VALLEY FARMS F8	PR
296415	WELL	PR	07/11/2013	GW	045-16012	VALLEY FARMS FEDERAL F14	PR
301818	WELL	PR	04/04/2013	GW	045-18286	Valley Farms F-1H	PR

**General Comment:**[Inspection is for odor complaint in area](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

# 1

Comment: Corrective Action: Date: 

Type: Horizontal Heated Separator

# 10

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 8

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 0

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLS	STEEL AST		39.525282,-107.642649
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

**Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	300 BBLs	STEEL AST		39.525362,-107.642555	
Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID:	291065	Type:	WELL	API Number: 045-14284 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	291066	Type:	WELL	API Number: 045-14285 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	291067	Type:	WELL	API Number: 045-14286 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	291072	Type:	WELL	API Number: 045-14289 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	291073	Type:	WELL	API Number: 045-14290 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	296414	Type:	WELL	API Number: 045-16011 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	296415	Type:	WELL	API Number: 045-16012 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		
Facility ID:	301818	Type:	WELL	API Number: 045-18286 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:		Date:		

--

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
		Culverts	Pass			
Gravel	Pass					
Rip Rap	Pass					
Sediment Traps	Pass					
Berms	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT