

# Inspection Photos

04/27/2017

Operator: Diversified Operating Corp #24461

Location ID: 409213

Inspection Doc. Number: 682501947

Weld County, CO

SESW Section 21 T8N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Diversified  
Location ID: 409213



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Diversified  
Location ID: 409213



**Photo 2:** Photo taken from the location, facing west. Photo shows areas of the location that remain bare with no evidence of desirable perennial vegetative germination.

Inspection Photos  
Operator: Diversified  
Location ID: 409213



**Photo 3:** Photo taken from the areas of the access road, to the immediate northwest of the location, facing north. Photo shows large gully that had formed.



**Photo 4:** Photo taken from the areas of the access road, to the immediate northwest of the location, facing northeast. Photo shows large gully that had formed.