

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401268322

Receive Date:

04/28/2017

Report taken by:

BOB CHESSON

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

### OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>		Operator No: <u>69175</u>	<b>Phone Numbers</b>
Address: <u>1775 SHERMAN STREET - STE 3000</u>			Phone: <u>(303) 860-5800</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>	Mobile: <u>( )</u>
Contact Person: <u>Karen Olson</u>		Email: <u>Karen.Olson@pdce.com</u>	

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 8964 Initial Form 27 Document #: 2314287

#### PURPOSE INFORMATION

- |  |  |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination                                       | <input checked="" type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water        |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure                  | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation                            | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project                                  |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste                      | <input type="checkbox"/> Rule 906.c.: Director request   |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____   |

#### SITE INFORMATION

N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>319321</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>RUPERT-64N65W 9NWSE</u>		Latitude: <u>40.325046</u>	Longitude: <u>-104.665698</u>
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: <u>NWSE</u>	Sec: <u>9</u>	Twp: <u>4N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

#### SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use CULTIVATED

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

#### Other Potential Receptors within 1/4 mile

Water well 380'N of tank battery. Occ bldg 1575'SW, nearest surf water 2350'W of location.

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☒ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
	GROUNDWATER	Refer to Fig 4 and Table 2	Drilling and groundwater sampling
	SOILS	Refer to Figs 2 & 3 and Table 1	Excavation and soil sampling

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On February 12, 2014, a historic release was discovered during the removal of a buried produced water vessel at the Rupert 1, 2, 32-8 (API# 05-123-11064) tank battery. A Form 19 was submitted on June 27, 2014 and the COGCC assigned Spill Tracking Number 400635216. A topographic map of the site is included as Figure 1.

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☐ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

#### Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

#### Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 0  
Number of soil samples exceeding 910-1             
Was the areal and vertical extent of soil contamination delineated?             
Approximate areal extent (square feet)           

### NA / ND

           Highest concentration of TPH (mg/kg)             
           Highest concentration of SAR             
           BTEX > 910-1             
           Vertical Extent > 910-1 (in feet)           

### Groundwater

Number of groundwater samples collected 11  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) 10'  
Number of groundwater monitoring wells installed 11  
Number of groundwater samples exceeding 910-1 0

ND Highest concentration of Benzene (µg/l)             
ND Highest concentration of Toluene (µg/l)             
ND Highest concentration of Ethylbenzene (µg/l)             
ND Highest concentration of Xylene (µg/l)             
NA Highest concentration of Methane (mg/l)           

### Surface Water

0 Number of surface water samples collected  
           Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)            Volume of liquid waste (barrels)           

☒ Is further site investigation required?

PDC feels that no further site investigation is required at this time. Temporary monitoring well locations are illustrated on Figure 4. Soil analytical results are summarized on Table 1 and groundwater analytical results are summarized on Table 2.

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## **SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

The source area was previously excavated and impacted material was transported and disposed of as described in the Form 19. The excavation extent and soil and groundwater sample locations are illustrated on Figures 2 and 3.

## **REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Monitored natural attenuation (MNA) will be the selected remediation strategy for the site beginning the first quarter 2017. Quarterly groundwater monitoring will continue until four consecutive quarters of monitoring data indicate BTEX concentrations are in compliance with the applicable COGCC Table 910-1 groundwater standards.

## **Soil Remediation Summary**

### ☐ In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

### ☐ Ex Situ

\_\_\_\_\_ Excavate and offsite disposal  
\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_  
\_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

## **Groundwater Remediation Summary**

☐ \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
☐ \_\_\_\_\_ Chemical oxidation  
☐ \_\_\_\_\_ Air sparge / Soil vapor extraction  
Yes \_\_\_\_\_ Natural Attenuation  
☐ \_\_\_\_\_ Other \_\_\_\_\_

## **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was encountered during excavation and drilling activities at approximately 15 feet below ground surface (bgs). PDC will continue quarterly groundwater sampling at the thirteen monitoring wells to monitor residual petroleum hydrocarbon impacts in groundwater using USEPA Method 8260. Groundwater monitoring will continue until four consecutive quarters of BTEX concentrations in compliance with COGCC Table 910-1 groundwater standards are achieved.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:** ☒ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other \_\_\_\_\_

**Report Type:** ☒ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☐ Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

Do all soils meet Table 910-1 standards? \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? \_\_\_\_\_

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The area where the excavation is located is used as an equipment access area to the tank battery location and consists of road base. The excavation has been backfilled and compacted with clean material and the ground surface was contoured to match pre-existing conditions. Subsequent to attainment of closure, the temporary monitoring wells will be plugged and abandoned.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). \_\_\_\_\_

Date of commencement of Site Investigation. 02/13/2014

Date of completion of Site Investigation. 06/26/2014

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 05/27/2014

Date of completion of Remediation. \_\_\_\_\_

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

### OPERATOR COMMENT

Based on historic analytical results, PDC Energy is requesting a reduction in the quarterly monitoring well network. Monitoring wells BH02/02R, BH06, BH07, and BH08 have exhibited seven or more quarters of constituent concentrations below COGCC Table 910-1 groundwater standards (Figure 2). Contingent on COGCC approval, removal of the selected monitoring wells would be conducted in the second quarter 2017.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Karen Olson

Title: Senior EHS Manager

Submit Date: 04/28/2017

Email: Karen.Olson@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: BOB CHESSON

Date: 04/28/2017

Remediation Project Number: 8964

### COA Type

### Description

--	--

## Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

### Att Doc Num

### Name

401268322	FORM 27-SUPPLEMENTAL-SUBMITTED
401268324	MONITORING REPORT
401269745	SITE MAP

Total Attach: 3 Files

## General Comments

### User Group

### Comment

### Comment Date

Environmental	Based on the information presented the COGCC staff agrees to the removal of ground water monitoring wells BH02R, BH06, BH07, and BH08 from the existing monitoring network for this remediation.	04/28/2017
---------------	--	------------

Total: 1 comment(s)