

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: 212608 Type: WELL API Number: 061-05061 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>-18"</u> (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg <u>0 PSIG</u>	Previous Test Pressure _____	Inj Zone: <u>ABCK</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>04/25/2013</u>
			AnnMTReq: <u>NO</u>

Comment: CASING HAD A STRONG VACUUM THAT DIED WITHIN 30 SECONDS. TBG IJ @ -18 PSIG

Corrective Action: _____ Date: _____

Method of Injection: GRAVITY FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT