

Location			
Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Sticker and stencil on tank		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Tumble weeds in fence around location. Remove old tumble weeds		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 212806 Type: WELL API Number: 061-06166 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is SI at time of inspection. Passing MIT performed 9/13/12. MIT to maintain SI/TA status will be due 9/13/17

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Access is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT