

Reclamation Inspection

April 27, 2017

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 440192

Weld County, CO

NENW Section 35 T12N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pismo East
Location ID: 440192



2015 aerial imagery using COGCC GISOnline database illustrating the Pismo East location in relation to the MLVT location approximately 0.54 miles to the east.

Inspection Photos
Location Name: Pismo East
Location ID: 440192



Photo 1. Photo taken from north of the MLVT location, facing South. A water hose travels west from this MLVT location to the Pismo East location. It should be noted this is a 54,000 bbl water tank based on the label that was present on the tank.