



**Location**

Overall Good:

**Signs/Marker:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
|                    | Type WELLHEAD |       |  |
| Comment:           |               |       |  |
| Corrective Action: |               | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

|                          |     |       |  |  | corrective date |
|--------------------------|-----|-------|--|--|-----------------|
| Type: Progressive Cavity | # 1 |       |  |  |                 |
| Comment:                 |     |       |  |  |                 |
| Corrective Action:       |     | Date: |  |  |                 |
| Type: Gas Meter Run      | # 1 |       |  |  |                 |
| Comment:                 |     |       |  |  |                 |
| Corrective Action:       |     | Date: |  |  |                 |
| Type: Deadman # & Marked | # 3 |       |  |  |                 |
| Comment:                 |     |       |  |  |                 |
| Corrective Action:       |     | Date: |  |  |                 |
| Type: Vertical Separator | # 1 |       |  |  |                 |
| Comment:                 |     |       |  |  |                 |
| Corrective Action:       |     | Date: |  |  |                 |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 272742 Type: WELL API Number: 071-08110 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type:      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: 30' x 60'

Corrective Action

Date:

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
|         | 278524      | 1175495    |                 |
|         | 278524      | 1175495    |                 |

| Monitoring: | Monitoring Type | Comment` |
|-------------|-----------------|----------|
|             | Chain           |          |