

Photo#1:

Sediment trap Drain area at SW edge of Pad



Photo#2:

Close up of Rocked Drain area



April 28, 2017

Photo#3:

SW is undercutting Rock armor



Photo#4:

View up to Pad from below Drain



April 28, 2017