


Photo#1:

View of Location from Entry to NE



Photo#2:

Newer Interim Reclamation adjacent to Entry




April 28, 2017

Photo#3:

Plastic Blanket netting has become Debris across NE Fill Slope



Photo#4:



April 28,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#335480

Photo#5:

Ball of netting at base of Fill slope (snow flakes in Pic).



Photo#6:

Unused Pipe on Location.



April 28,2017