

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2017

Submitted Date:

05/02/2017

Document Number:

666803138**FIELD INSPECTION FORM**
 Loc ID 334616 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211140	WELL	PR	12/17/1994	GW	045-06899	PARKER RANCH 22-7	PR
258802	WELL	PR	06/01/2002	GW	045-07657	ROSE RANCH 22-8 (G22)	SI
258803	WELL	PR	06/01/2002	GW	045-07658	ROSE RANCH 22-2 (G22)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

3

Comment: Corrective Action: Date:

Type: Plunger Lift

1

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment: Centralized battery						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:								
Corrective Action:							Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS	
CONDENSATE		3	300 BBLS	STEEL AST			39.433628,-107.759894	
Comment:								

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 211140 Type: WELL API Number: 045-06899 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 258802 Type: WELL API Number: 045-07657 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last production numbers posted Feb 2017

Corrective Action:

Date: _____

Facility ID: 258803 Type: WELL API Number: 045-07658 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
		Gravel	Pass			
Gravel	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT