

**Inspection Photos**  
**Location Name: Craig 1-7**  
**API: 05-081-06217**



**Photo 1. View of location at entrance facing north.**



**Photo 2. Stained soil at exhaust, lube oil containers without secondary containment.**

Inspection Photos  
Location Name: Craig 1-7  
API: 05-081-06217



**Photo 3. Unlabeled container with no secondary containment.**



**Photo 4. Stained soil at wellhead.**