

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2017

Submitted Date:

05/03/2017

Document Number:

680301918

FIELD INSPECTION FORM

Loc ID 312138 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218713	WELL	PR	04/26/2007	OW	075-05445	FRASCO 1-B	PA

General Comment:

P&A Day (4) No problems indicated. Contractor on-site removing contents from separator.

Location

Lease Road:			
Type	Access		
comment:	Satisfactory		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Other	# 0			
Comment:	No change in equipment inventoried.			
Corrective Action:		Date:		

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 218713 Type: WELL API Number: 075-05445 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Ranger

Contractor Phone: 713-935-8900

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 5449'

Cement Volume (sx): 2

Good Return During Job: _____

Cement Type: _____

Comment: Brought in good workstring, PU TBG @ 5413' circulated fluids out. Pressured casing to 500 psi for (5) min. Preparing for setting plugs as soon as equipment & weather conditions allow. No problems indicated

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT