



**Photo 1:** View of the project area from the northeastern corner facing center.



**Photo 2:** View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*) and the shrub rubber rabbitbrush (*Chrysothamnus nauseosus*) Hundreds of musk thistles are growing along the outer edges of the eastern portion of the project area.



**Photo 3: View of wattles in the western portion of the project area. These are filling with sediment and will soon need maintenance.**



**Photo 4: View of the edge of placed wattles exposed soils and evidence of sediment deposition below. Musk thistles are also growing in this portion of the project area.**



**Photo 5: Closeup view of musk thistles within the eastern portion of the project area.**