

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2017

Submitted Date:

05/03/2017

Document Number:

679700434**FIELD INSPECTION FORM**
 Loc ID 418514 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418515	WELL	PR	09/01/2014	OW	123-31940	DRAKE II18-04	EI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
Produced Water	Tank	<= 1 bbl		
Comment: Evidence of produced water vault overflow < 5bbls in lined secondary containment				
Corrective Action: Implement corrective measures to prevent overflow of produced water vessel. Cleanup oily residue on tank.			Date: 06/03/2017	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type			corrective date
Horizontal Separator	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: ALLISON, RICK

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 418515 Type: WELL API Number: 123-31940 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700435	Produced water vessel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138590