

Reclamation and Stormwater Inspection

May 2, 2017

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 439530

Weld County, CO

NENE Section 14 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURROUGHS NORTH /NENE PAD #1

Location ID: 439530



Photo 1. Photo taken from the northeast perimeter of the location, facing West. Ditch and berm BMP has been installed around the entire perimeter of the location in conjunction with other BMPs and appears to be properly functioning.



Photo 2. Photo taken from the northwestern perimeter of the location, facing West. Ditch and berm BMP has been installed in conjunction with check dams prior to the sediment trap.

Inspection Photos

Location Name: BURROUGHS NORTH /NENE PAD #1

Location ID: 439530



Photo 3. Photo taken from the northwest perimeter of the location, facing West. Sediment trap has been installed with both inlet and outlet protection.



Photo 4. Photo taken from the northwest perimeter of the location, facing South. Sediment trap has been installed with both inlet and outlet protection, as well as check dams.

Inspection Photos

Location Name: BURROUGHS NORTH /NENE PAD #1

Location ID: 439530



Photo 5. Photo taken from the western location, facing East. Gravel berm has been constructed around the outer well pad area and fill slopes have been properly tracked.



Photo 6. Photo taken from the south perimeter of the location, facing West. Appears soil material has been moved and because of flow line activity. Unconsolidated soil material needs to be stabilized to prevent sediment discharge off location.

Inspection Photos

Location Name: BURROUGHS NORTH /NENE PAD #1

Location ID: 439530



Photo 7. Photo taken from the southeastern location, facing West. Topsoil has been salvaged, stored and temporarily stabilized along the southern perimeter of the location.



Photo 8. Photo taken from the southeast perimeter of the location, facing North. Ditch and berm BMP has been installed.