

Reclamation and Stormwater Inspection

May 2, 2017

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 439635

Weld County, CO

NESE Section 14 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURROUGHS NESE PRODUCTION FACILITY /PAD #1

Location ID: 439635



Photo 1. Photo taken from the northeastern perimeter of the location, facing North. Ditch and berm BMP has been installed around the location in conjunction with other BMPs and appears to be properly functioning.



Photo 2. Photo taken from the northern perimeter of the location, facing West. Topsoil has been salvaged, stored and temporarily stabilized along the northern perimeter of the location.

Inspection Photos

Location Name: BURROUGHS NESE PRODUCTION FACILITY /PAD #1

Location ID: 439635



Photo 3. Photo taken from the northwestern perimeter of the location, facing South. Ditch and berm BMP has been installed in conjunction with check dams. BMP area appears to be wider than other portions and may function as a retention area.



Photo 4. Photo taken from the western perimeter of the location, facing South. BMP area appears to be wider than other portions and may function as a retention area; however, the outer berm appears to be shallow. This production location is not being reduced in size (5.41 acres). Therefore, the Operator may want to consider additional BMPs or modify the existing BMP.

Inspection Photos

Location Name: BURROUGHS NESE PRODUCTION FACILITY /PAD #1

Location ID: 439635



Photo 5. Photo taken from the southwestern perimeter of the location, facing East. Ditch and berm BMP has been installed in conjunction with check dams. Minor wind erosion appears to be evident along portions of the location which may require additional stabilization BMPs.



Photo 6. Photo taken from the southeastern perimeter of the location, facing North. Ditch and berm BMP has been installed.