

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2017

Submitted Date:

05/03/2017

Document Number:

685302965**FIELD INSPECTION FORM**

Loc ID 333954 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 19160
 Name of Operator: CONOCO PHILLIPS COMPANY
 Address: P O BOX 2197
 City: HOUSTON State: TX Zip: 77252-

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Walker, Crystal	505-326-9837	Crystal.Walker@cop.com	SW Inspection Reports
Brock, Christine		Christine.Brock@conocophillips.com	SW Inspection Reports
Busse, Dollie	505-324-6104	dollie.l.busse@conocophillips.com	SW Inspection Reports
Prasanna, Sonu	832-486-2299	Sonu.Prasanna@conocophillips.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261505	WELL	PR	05/23/2002	GW	067-08641	ARGENTA 34-10 33-3	PR

General Comment:

[Witnessed Bradenhead testing.](#)

Inspected Facilities

Facility ID: 261505 Type: WELL API Number: 067-08641 Status: PR Insp. Status: PR

BradenHead

Comment: Witnessed Bradenhead testing. Initial Braden Head pressure reading 0.0 PSI, Casing 32 PSI, Tubing 18 PSI. Instantaneous Braden Head reading 0.0 PSI.

Corrective Action:

Date: