

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2017

Submitted Date:

05/04/2017

Document Number:

675103562

**FIELD INSPECTION FORM**

Loc ID 335713 Inspector Name: GRANAHAN, KYLE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: PO BOX 6501  
City: ENGLEWOOD State: CO Zip: 80155

**Findings:**

19 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	Piceance Creek insp
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp
Kardos, Kelly		kelly_kardos@xtoenergy.com	Piceance Creek insp

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290091	WELL	PR	07/01/2013	GW	103-11009	FREEDOM UNIT 297-17A8	PR
290092	WELL	PR	07/01/2013	GW	103-11008	FREEDOM UNIT 297-17A4	PR
290093	WELL	PR	07/01/2013	GW	103-11007	FREEDOM UNIT 297-17A5	PR
290094	WELL	PR	07/01/2013	GW	103-11006	FREEDOM UNIT 297-17A3	PR
290095	WELL	PR	07/01/2013	GW	103-11005	FREEDOM UNIT 297-17A7	PR
290096	WELL	PR	07/01/2013	GW	103-11004	FREEDOM UNIT 297-17A6	SI
290097	WELL	PR	07/01/2013	GW	103-11003	FREEDOM UNIT 297-17A9	PR
290098	WELL	PR	06/01/2013	GW	103-11002	FREEDOM UNIT 297-17A1	SI
290099	WELL	PR	07/01/2013	GW	103-11001	FREEDOM UNIT 297-17A2	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-4117

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical tote with secondary containment		
Corrective Action:		Date:	
Type: Horizontal Separator	# 2		
Comment:	2 - quad manifolds feed to 1 separator/meter house		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID: 290091	Type: WELL	API Number: 103-11009	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR - via plunger lift with choke - no leaks/venting - remote monitoring present				
Corrective Action:				Date:
Facility ID: 290092	Type: WELL	API Number: 103-11008	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR - via plunger lift with choke - no leaks/venting - remote monitoring present				
Corrective Action:				Date:
Facility ID: 290093	Type: WELL	API Number: 103-11007	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR - via plunger lift with choke - no leaks/venting - remote monitoring present				
Corrective Action:				Date:
Facility ID: 290094	Type: WELL	API Number: 103-11006	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR - via plunger lift with choke - no leaks/venting - remote monitoring present				
Corrective Action:				Date:
Facility ID: 290095	Type: WELL	API Number: 103-11005	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR - via plunger lift with choke - no leaks/venting - remote monitoring present				
Corrective Action:				Date:
Facility ID: 290096	Type: WELL	API Number: 103-11004	Status: PR	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: EQUIPMENT ONSITE				
Comment: Well SI at time of inspection - valves on well LOTO, remote monitoring present				
Corrective Action:				Date:
Facility ID: 290097	Type: WELL	API Number: 103-11003	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR - via plunger lift with choke - no leaks/venting - remote monitoring present				
Corrective Action:				Date:
Facility ID: 290098	Type: WELL	API Number: 103-11002	Status: PR	Insp. Status: SI

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection - valves LOTO, remote monitoring present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 290099    Type: WELL    API Number: 103-11001    Status: PR    Insp. Status: PR

**Producing Well**

Comment: PR - via plunger lift with choke - no leaks/venting - remote monitoring present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					
Berms	Pass					
Check Dams	Pass					
Retention Ponds	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	291419	1433691	
	291419	1433691	