

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2017

Submitted Date:

05/01/2017

Document Number:

674200048

FIELD INSPECTION FORM

Loc ID 445139 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445132	WELL	DG	04/06/2017		123-42900	Cecil's Kersey Farm 17K-334	DG
445133	WELL	DG	03/25/2017		123-42901	Cecil's Kersey Farm 17K-204	DG
445134	WELL	DG	04/22/2017		123-42902	Cecil's Kersey Farm 17B-212	DG
445135	WELL	DG	03/19/2017		123-42903	Cecil's Kersey Farm 17K-402	DG
445137	WELL	DG	04/11/2017		123-42905	Cecil's Kersey Farm 17K-332	DG
445140	WELL	DG	03/31/2017		123-42907	Cecil's Kersey Farm 17K-232	DG
448416	WELL	DG	04/16/2017		123-43895	Cecil's Kersey Farm 17B-214	DG

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment	#		corrective date
Comment:	APPROX 32' SOUND WALLS ON SOUTH AND WEST END OF LOCATION FOR SOUND MITIGATION		
Corrective Action:			Date: _____

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: _____

Flaring:

Type	Field Flare		
Comment:	NOT IN USE AT TIME OF INSPECTION		
Corrective Action:			Date: _____

Inspected Facilities

Facility ID: 445132 Type: WELL API Number: 123-42900 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: ENSIGN 152 Pusher/Rig Manager: VAUGHN STAPLES
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: LAND FARMED

Comment: COMPLETING 10TH WELL THIS WEEK ALL LIGHTING POINTED DOWN AND TOWARD THE CENTER OF LOCATION

Corrective Action: _____ Date: _____

Facility ID: 445133 Type: WELL API Number: 123-42901 Status: DG Insp. Status: DG

Facility ID: 445134 Type: WELL API Number: 123-42902 Status: DG Insp. Status: DG

Facility ID: 445135 Type: WELL API Number: 123-42903 Status: DG Insp. Status: DG

Facility ID: 445137 Type: WELL API Number: 123-42905 Status: DG Insp. Status: DG

Facility ID: 445140 Type: WELL API Number: 123-42907 Status: DG Insp. Status: DG

Facility ID: 448416 Type: WELL API Number: 123-43895 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401271240	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4136254