

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2017

Submitted Date:

05/01/2017

Document Number:

674703877

**FIELD INSPECTION FORM**

Loc ID 335881 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name     | Phone | Email                        | Comment |
|------------------|-------|------------------------------|---------|
| Elsener, Garrett |       | garrett@caerusoilandgas.com  |         |
| McKee, Michael   |       | MMckee@caerusoilandgas.com   |         |
| Janicek, Jake    |       | JJanicek@caerusoilandgas.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 290068      | WELL | PR     | 12/31/2008  | GW         | 045-13978 | CHEVRON 33D-7D | PR          |
| 290069      | WELL | PR     | 12/31/2008  | GW         | 045-13977 | CHEVRON 33B-7D | PR          |
| 290070      | WELL | PR     | 12/31/2008  | GW         | 045-13976 | CHEVRON 32B-7D | PR          |
| 290071      | WELL | PR     | 03/31/2009  | GW         | 045-13975 | CHEVRON 22A-7D | PR          |
| 290072      | WELL | PR     | 10/01/2008  | GW         | 045-13974 | CHEVRON 23B-7D | PR          |
| 290073      | WELL | PR     | 12/31/2008  | GW         | 045-13973 | CHEVRON 33A-7D | PR          |
| 290074      | WELL | PR     | 12/31/2008  | GW         | 045-13972 | CHEVRON 32A-7D | PR          |
| 290075      | WELL | PR     | 12/31/2008  | GW         | 045-13971 | CHEVRON 32D-7D | PR          |
| 290076      | WELL | PR     | 10/01/2015  | GW         | 045-13970 | CHEVRON 23A-7D | PR          |
| 290077      | WELL | PR     | 10/01/2008  | GW         | 045-13969 | CHEVRON 21D-7D | PR          |
| 290078      | WELL | PR     | 12/31/2008  | GW         | 045-13968 | CHEVRON 22D-7D | PR          |

**General Comment:**

| Location   |   |        |             |
|--|---|--------|-------------|
| <b>Lease Road:</b>                                     |   |        |             |
| Type   | Main                                      |        |             |
| comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |
| Overall Good: <input checked="" type="checkbox"/>      |   |        |             |
| <b>Signs/Marker:</b>                                   |   |        |             |
| Type   | CONTAINERS                                |        |             |
| Comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |
| Type   | BATTERY                                   |        |             |
| Comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |
| Type   | WELLHEAD                                  |        |             |
| Comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |
| Type   | TANK LABELS/PLACARDS                      |        |             |
| Comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |
| Emergency Contact Number:                              |   |        |             |
| Comment:   | <input type="text" value="866-580-9382"/> |        |             |
| Corrective Action:                                     | <input type="text"/>                      |        | Date: _____ |
| <b>Good Housekeeping:</b>                              |   |        |             |
| Type   | TRASH                                     |        |             |
| Comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |
| Overall Good: <input checked="" type="checkbox"/>      |   |        |             |
| <b>Spills:</b>   |   |        |             |
| Type   | Area                                      | Volume |             |
| In Containment: No                                     |   |        |             |
| Comment:   | <input type="text"/>                      |        |             |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |             |
| <b>Fencing/:</b>                                       |   |        |             |
| Type   | WELLHEAD                                  |        |             |
| Comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |
| Type   | SEPARATOR                                 |        |             |
| Comment:   |   |        |             |
| Corrective Action:                                     |   |        | Date:       |

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |                             |       |                 |
|-----------------------------------|-----------------------------|-------|-----------------|
| <b>Equipment:</b>                 |                             |       | corrective date |
| Type: Ancillary equipment         | # 1                         |       |                 |
| Comment:                          | Chemical container at wells |       |                 |
| Corrective Action:                |                             | Date: |                 |
| Type: Bird Protectors             | # 5                         |       |                 |
| Comment:                          |                             |       |                 |
| Corrective Action:                |                             | Date: |                 |
| Type: Plunger Lift                | # 11                        |       |                 |
| Comment:                          |                             |       |                 |
| Corrective Action:                |                             | Date: |                 |
| Type: Horizontal Heated Separator | # 11                        |       |                 |
| Comment:                          |                             |       |                 |
| Corrective Action:                |                             | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 400 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| <b>Berms</b>       |          |                     |                     |             |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |    |  |  |       |
|--------------------|----|--|--|-------|
| <b>Venting:</b>    |    |  |  |       |
| Yes/No             | NO |  |  |       |
| Comment:           |    |  |  |       |
| Corrective Action: |    |  |  | Date: |

|                    |  |  |  |       |
|--------------------|--|--|--|-------|
| <b>Flaring:</b>    |  |  |  |       |
| Type               |  |  |  |       |
| Comment:           |  |  |  |       |
| Corrective Action: |  |  |  | Date: |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 290068         | Type: | WELL | API Number: | 045-13978 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 290069         | Type: | WELL | API Number: | 045-13977 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 290070         | Type: | WELL | API Number: | 045-13976 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 290071         | Type: | WELL | API Number: | 045-13975 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 290072         | Type: | WELL | API Number: | 045-13974 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 290073         | Type: | WELL | API Number: | 045-13973 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 290074         | Type: | WELL | API Number: | 045-13972 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 290075         | Type: | WELL | API Number: | 045-13971 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |

|                              |                       |                              |                   |                         |
|------------------------------|-----------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>290076</u>   | Type: <u>WELL</u>     | API Number: <u>045-13970</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b> |                       |                              |                   |                         |
| Comment:                     | <u>Producing well</u> |                              |                   |                         |
| Corrective Action:           |                       | Date:                        |                   |                         |
| Facility ID: <u>290077</u>   | Type: <u>WELL</u>     | API Number: <u>045-13969</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b> |                       |                              |                   |                         |
| Comment:                     | <u>Producing well</u> |                              |                   |                         |
| Corrective Action:           |                       | Date:                        |                   |                         |
| Facility ID: <u>290078</u>   | Type: <u>WELL</u>     | API Number: <u>045-13968</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| <b><u>Producing Well</u></b> |                       |                              |                   |                         |
| Comment:                     | <u>Producing well</u> |                              |                   |                         |
| Corrective Action:           |                       | Date:                        |                   |                         |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction       | Pass            |                         |                       |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
| Gravel           | Pass            |                         |                       |  |                          |         |
| Seeding          | Pass            |                         |                       |  |                          |         |
|                  |                 | Gravel                  | In Process            |  |                          |         |
|                  |                 | Ditches                 | Pass                  |  |                          |         |
| Berms            | Pass            |                         |                       |  |                          |         |
|                  |                 | Culverts                | Pass                  |  |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 401270754    | INSPECTION SUBMITTED           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4135980">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4135980</a> |
| 674703882    | Location photo CHEVRON #22D-7D | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4135976">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4135976</a> |