

Photo#1:
View North over Location center.
(Surface Owner in Photos)



Photo#2:
View South over Location Center.



May 3,2017

Photo#3:
View East over Location center



Photo#4:
View West over Location. center
(Surface Owner in Photo)



May 3,2017



Photo#5:

Close up of Vegetation in Disturbed area

Vegetation in Reclaimed area was assessed to be 80% of that in Reference area.

Photo#6:

Close up of Vegetation in Reference Area



May 3,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Webb API# 077-08283