

Photo#1:  
View North over Location.



Photo#2:  
View South over Location.



May 3,2017

Photo#3:  
Culvert in place at Entry into Location



Photo#4:  
Debris on Location



May 3,2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Black Hills PA API# 077-08368

Photo#5:  
Rock Pile to east of Entry



Photo#6:  
Slash Pile on East edge of Location.



May 3,2017

Photo#7:  
View SW up Access Rd leading out of Location



Photo#8:  
Compacted Pad area



May 3,2017

Photo#9:

Thistle emerging on Site



Photo#10:

Houndstongue emerging on Site



May 3,2017

Photo#11:

Old & new growth of Burdock that infests Site.



May 3,2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Black Hills PA API# 077-08368