

Photo#1:

View to NE over Location. Pipe is said to now be Land Owner's.



Photo#2:

View East into Location. Access Rd immediate to Pad has been reclaimed, though vehicle access is visible.



May 3,2017

Photo#3:

Seeding installed in Fall 2016 is emerging through straw mulch across Location.



May 3,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA API# 077-08359