

# Final Reclamation and Stormwater Inspection

April 27, 2017

Operator: SLAWSON EXPLORATION COMPANY INC- #10334

API: 05-123-31937

Weld County, CO

SESE Section 30 T12N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Riva Ridge #30-12-66  
API: 05-123-31937



**Photo 1.** Photo taken from the approximate center of location, facing West. No evidence of wellbore or disturbance at location.



**Photo 2.** Photo taken from the approximate center of location, facing North. No evidence of wellbore or disturbance at location.

Inspection Photos  
Location Name: Riva Ridge #30-12-66  
API: 05-123-31937



**Photo 3.** Photo taken from the approximate center of location, facing East. No evidence of wellbore or disturbance at location.



**Photo 4.** Photo taken from the approximate center of location, facing South. No evidence of wellbore or disturbance at location.

Inspection Photos  
Location Name: Riva Ridge #30-12-66  
API: 05-123-31937



**Photo 5.** Close-up photo taken from the approximate center of location. No evidence of wellbore or disturbance at location. Location appears reflective of reference area conditions.



**Photo 6.** Reference photo taken south of location, facing East. Location appears reflective of reference area conditions.