

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2017

Submitted Date:

05/09/2017

Document Number:

675103570**FIELD INSPECTION FORM**

Loc ID 335900 Inspector Name: GRANAHAN, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp
Kardos, Kelly		kelly_kardos@xtoenergy.com	Piceance Creek insp
Reid, Van		van_reid@xtoenergy.com	Piceance Creek insp

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293656	WELL	AL	12/31/2013	LO	103-11129	Freedom Unit 297-32A10	AL
293657	WELL	AL	12/31/2013	LO	103-11130	Freedom Unit 297-32A9	AL
293658	WELL	AL	12/31/2013	LO	103-11131	Freedom Unit 297-32A8	AL
293659	WELL	AL	12/31/2013	LO	103-11132	Freedom Unit 297-32A7	AL
293660	WELL	AL	12/31/2013	LO	103-11133	Freedom Unit 297-32A6	AL
293661	WELL	PR	10/04/2013	GW	103-11134	FREEDOM UNIT 297-32A5	SI
293662	WELL	PR	10/04/2013	GW	103-11135	FREEDOM UNIT 297-32A4	SI
293663	WELL	PR	10/04/2013	GW	103-11136	FREEDOM UNIT 297-32A3	SI
293664	WELL	PR	07/01/2013	GW	103-11137	FREEDOM UNIT 297-32A2	SI
293665	WELL	PR	09/01/2016	GW	103-11138	FREEDOM UNIT 297-32A1	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-4117

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chem tote with secondary containment		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		

Comment:	Separator/meter combo		Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 8			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Poly lined earth berm			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 293656 Type: WELL API Number: 103-11129 Status: AL Insp. Status: ALFacility ID: 293657 Type: WELL API Number: 103-11130 Status: AL Insp. Status: ALFacility ID: 293658 Type: WELL API Number: 103-11131 Status: AL Insp. Status: ALFacility ID: 293659 Type: WELL API Number: 103-11132 Status: AL Insp. Status: ALFacility ID: 293660 Type: WELL API Number: 103-11133 Status: AL Insp. Status: ALFacility ID: 293661 Type: WELL API Number: 103-11134 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI - no leaks/venting - remote pressure monitoring presentCorrective Action:  Date: Facility ID: 293662 Type: WELL API Number: 103-11135 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI - no leaks/venting - remote pressure monitoring presentCorrective Action:  Date: Facility ID: 293663 Type: WELL API Number: 103-11136 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI - no leaks/venting - remote pressure monitoring presentCorrective Action:  Date: Facility ID: 293664 Type: WELL API Number: 103-11137 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI - no leaks/venting - remote pressure monitoring presentCorrective Action:  Date: Facility ID: 293665 Type: WELL API Number: 103-11138 Status: PR Insp. Status: SI

<b>Idle Well</b>		
Purpose: <input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT ONSITE
Comment:	<a href="#">SI - no leaks/venting - remote pressure monitoring present</a>	
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					
Gravel	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	293831	1433757	