

Inspection Photos
Location Name: Bighole Gulch Unit 3
API: 05-081-07597



Photo 1. View at entrance to location facing north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 673404545

Inspection Photos
Location Name: Bighole Gulch Unit 3
API: 05-081-07597



Photo 2. EOG Y on sticker, previous operator emergency number still on sign with no updated number.



Photo 3. Yates listed as operator on tank labels.