

Inspection Photos

05/1/2017

Operator: Noble Energy Inc #100322

Location ID: 327002

Inspection Doc. Number: 682501973

Weld County, CO

SESE Section 34 T9N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Noble Energy Inc #100322
Location ID: 327002



Photo 1: Photo taken from the south end of the location, facing west. Photo shows pipe riser and debris has not been removed from location.