

Construction and Stormwater Inspection

May 5, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 442643

Arapahoe County, CO

SESE Section 4 T4S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: B&D Land 4-64 4 /1H
Location ID: 442643



Photo 1. Photo taken from the entrance of location, facing Northwest. Topsoil has been salvaged and stored along the southern perimeter of the location. Temporary stormwater BMP installed around the entire location in the form of a filtrex wattle.



Photo 2. Photo taken from the southeastern location, facing North. Diversion ditch has been installed along the eastern perimeter of the well pad location.

Inspection Photos
Location Name: B&D Land 4-64 4 /1H
Location ID: 442643



Photo 3. Photo taken from the northeastern location, facing West. Ditch and berm BMP has been installed along the northern perimeter of the well pad location.



Photo 4. Photo taken from the northwestern location, facing South. Operator is making another pass along the western cut slope.

Inspection Photos
Location Name: B&D Land 4-64 4 /1H
Location ID: 442643



Photo 5. Photo taken from the southwest location, facing West. Temporary stormwater BMP installed around the entire location in the form of a filtrex wattle.



Photo 6. Photo taken from the southwest location, facing East. Temporary stormwater BMP installed around the entire location in the form of a filtrex wattle.