

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401274672

Date Received:

05/11/2017

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

449978

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: PDC ENERGY INC	Operator No: 69175	Phone Numbers
Address: 1775 SHERMAN STREET - STE 3000		Phone: (970) 506-9272
City: DENVER	State: CO	Zip: 80203
Contact Person: Zack Liesenfeld		Mobile: (970) 373-6581
		Email: Zack.Liesenfeld@pdce.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401254471

Initial Report Date: 04/10/2017 Date of Discovery: 04/07/2017 Spill Type: Historical Release

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWSW SEC 29 TWP 6N RNG 64W MERIDIAN 6

Latitude: 40.454710 Longitude: -104.582670

Municipality (if within municipal boundaries): County: WELD

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 330611

☐ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: CROP LAND

Other(Specify):

Weather Condition: Sunny and warm

Surface Owner: FEE

Other(Specify):

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A historic release was discovered on the Uhrich 13-29 while abandoning the production facility. Current remediation efforts are mitigating impacts.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
4/8/2017	COGCC	Rick Allison	-	Via email
4/8/2017	Weld County	Roy Rudisill	-	Via email
4/7/2017	Land owner	NA	-	Via phone call

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 05/04/2017		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL			<input checked="" type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 53 Width of Impact (feet): 44

Depth of Impact (feet BGS): 24 Depth of Impact (inches BGS): _____

How was extent determined?

On April 7, 2017, a historic release was discovered below the separator during decommissioning activities at the Uhrich 13-29 production facility. Between April 10 and April 17, 2017, approximately 1,092 cubic yards of impacted material were removed and transported to the North Weld Waste Management Facility in Ault, Colorado for disposal under PDC waste manifests. Sixteen soil samples (SS03 – SS06 and SS09 - SS20) were collected from the sidewalls of the final extent of the excavation area at approximately 12 feet and 22 feet below ground surface (bgs). Soil samples were submitted to Summit Scientific Laboratories (Summit) for analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH) – gasoline range organics (GRO) by United States Environmental Protection Agency (USEPA) Method 8260, and TPH – diesel range organics (DRO) by USEPA Method 8015. Analytical results indicated constituent concentrations were below COGCC Table 910-1 standards in the sixteen soil sample locations. Groundwater was encountered in the excavation at approximately 24 feet bgs. Between April 18 and April 30, 2017, approximately 90 barrels of groundwater were recovered from the excavation using a vacuum truck and transported to a licensed disposal facility. On May 1, 2017, one groundwater sample (GW01) was collected from the excavation area and submitted to Summit for laboratory analysis of BTEX by USEPA Method 8260. Analytical results indicated dissolved phase BTEX concentrations were below COGCC Table 910-1 standards. The excavation extent and soil and groundwater sample locations are illustrated on Figure 2. Soil analytical data is summarized in Table 1 and groundwater analytical data is summarized in Table 2. Laboratory reports are provided in Attachment A. Based on the data described herein, PDC is requesting a No Further Action (NFA) determination for this release.

Soil/Geology Description:

Otero sandy loam, 1 to 3 percent slopes.

<u>Att Doc Num</u>	<u>Name</u>
401275521	TOPOGRAPHIC MAP
401275583	SITE MAP
401275871	ANALYTICAL RESULTS

Total Attach: 3 Files

<u>General Comments</u>		
<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)