

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/11/2017

Submitted Date:

05/11/2017

Document Number:

685502755**FIELD INSPECTION FORM**

Loc ID 320420 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email         | Comment                         |
|--------------|-------|---------------|---------------------------------|
| ,            |       | cogcc@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 203718      | WELL | PR     | 12/31/2007  | GW         | 001-09278 | HSR-VAN SCHAACK 13-33 | PR          |

**General Comment:**

**Location**

|                    |      |       |  |
|--------------------|------|-------|--|
| <b>Lease Road:</b> |      |       |  |
| Type               | Main |       |  |
| comment:           |      |       |  |
| Corrective Action  |      | Date: |  |

Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment: OK

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |                |       |  |
|--------------------|----------------|-------|--|
| <b>Fencing/:</b>   |                |       |  |
| Type               | WELLHEAD       |       |  |
| Comment:           | ROD IRON FENCE |       |  |
| Corrective Action: |                | Date: |  |

|                    |                                    |       |                 |
|--------------------|------------------------------------|-------|-----------------|
| <b>Equipment:</b>  |                                    |       | corrective date |
| Type: Plunger Lift | # 1                                |       |                 |
| Comment:           | INTERMITTER CONTROLLER ON WELLHEAD |       |                 |
| Corrective Action: |                                    | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Type               | Ignitor/Combustor |       |  |
| Comment:           |                   |       |  |
| Corrective Action: |                   | Date: |  |

| Inspected Facilities |        |                               |      |             |           |         |    |               |    |
|----------------------|--------|-------------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 203718 | Type:                         | WELL | API Number: | 001-09278 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |                               |      |             |           |         |    |               |    |
| Comment:             |        | PR                            |      |             |           |         |    |               |    |
| Corrective Action:   |        |                               |      |             |           |         |    | Date:         |    |
| BradenHead           |        |                               |      |             |           |         |    |               |    |
| Comment:             |        | BRADENHEAD PLUMBED TO SURFACE |      |             |           |         |    |               |    |
| Corrective Action:   |        |                               |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 685502756    | BATTERY EQUIPMENT AND WELLHEAD | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145412">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145412</a> |