

# Inspection Photos

05/11/2017

Operator: Bonanza Creek Energy #8960

Location ID: 305141

Inspection Doc. Number: 682501995

Weld County, CO

NWSE Section 22 T10N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 305141



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 305141



**Photo 2:** Photo taken from the east end of the location, facing southwest. Photo shows additional reclamation activities have been conducted; reclamation in process.



**Photo 3:** Photo taken from the east end of the location, facing northwest. Photo shows additional reclamation activities have been conducted; reclamation in process.