

Inspection Photos

05/11/2017

Operator: Bonanza Creek Energy #8960

Location ID: 305297

Inspection Doc. Number: 682501997

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Bonanza Creek Energy #8960
Location ID: 305297



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Bonanza Creek Energy #8960
Location ID: 305297



Photo 2: Photo taken from the north end of the Pad well, facing southeast. Photo shows Interim reclamation activities have not been conducted. Gravel/road base remains, location remains predominantly bare and exposed soil. Gravel will need to be removed, area will need to be reclaimed.



Photo 3: Photo taken from the north end of the Pad well, facing southwest. Photo shows Interim reclamation activities have not been conducted. Gravel/road base remains, location remains predominantly bare and exposed soil. Gravel will need to be removed, area will need to be reclaimed.

Inspection Photos
Operator: Bonanza Creek Energy #8960
Location ID: 305297



Photo 4: Photo taken from the location. Photo shows Interim reclamation activities have not been conducted. Gravel/road base remains, location remains predominantly bare and exposed soil. Gravel will need to be removed, area will need to be reclaimed.

Inspection Photos
Operator: Bonanza Creek Energy #8960
Location ID: 305297



Photo 4: 2015 Aerial imagery from COGCC GISOnline. Photo shows area on the south end of the location where PAD well 123-22765 existed has not been reclaimed. Areas no longer reasonably needed for production activities need to be reclaimed per 1003.b