

# Inspection Photos

05/11/2017

Operator: Bonanza Creek Energy #8960

Location ID: 427785

Inspection Doc. Number: 682501999

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 427785



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 427785



**Photo 2:** Photo taken from the east end of the location, facing west. Photo shows reclamation in process.



**Photo 3:** Photo taken from the east end of the location, facing southwest. Photo shows reclamation in process.