

Inspection Photos

05/11/2017

Operator: Bonanza Creek Energy #8960

Location ID: 437240

Inspection Doc. Number: 682502001

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Bonanza Creek Energy #8960
Location ID: 437240



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Bonanza Creek Energy #8960
Location ID: 437240



Photo 2: Photo taken from the eastern end of the interim area. Photo shows additional reclamation activities have been conducted on the location.