

# Inspection Photos

05/11/2017

Operator: Bonanza Creek Energy #8960

Location ID: 305298

Inspection Doc. Number: 682502006

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 305298



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 305298



**Photo 2:** Photo taken from the south end of the location, facing north. Photo shows location remains predominantly exposed soil.



**Photo 3:** Photo taken from the south end of the location, facing northeast. Photo shows location remains predominantly exposed soil.

Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 305298



**Photo 4:** Photo taken from the location. Photo shows location remains predominantly exposed soil. Gravel/road base does not appear to have been removed. 6 foot measuring stick for reference.



**Photo 5:** Photo shows vegetation over the reference area. Vegetation seen here predominantly a mix of blue grama, buffalo grass and various forb species. 6 foot measuring stick for reference.

Inspection Photos  
Operator: Bonanza Creek Energy #8960  
Location ID: 305298



**Photo 6:** Photo taken from the northeast end of the location, facing southwest. Photo shows location remains predominantly exposed soil. 6 foot measuring stick for reference.



**Photo 7:** Photo taken from the access road north of the location, facing south. Photo shows access road remains predominantly exposed soil.