

Photo#1:

Overview of Location from SW corner to NE.



May 11, 2017



Photo#2:

Vegetation is struggling in some sections of Cut & Fill Slopes.

Fill Slope



Photo#3:

Cut Slope



May 11, 2017



Photo#4:

Photo#5:

BMPS along North side of Location.



May 11, 2017