

Photo#1:  
Overview of Location from Entry to NE.



May 11, 2017

Photo#2:

Ditches, BMPs at either side of Access Rd Entry

Photo#3:



May 11, 2017

Photo#4:

Ditch at base of Cut Slope that catches Seep Water.



Photo#5:

Retention Pond at North corner of Location.



May 11, 2017

Photo#6:

Cut Slope along SE side of Site



Photo#7:

Fill slope along NW side of Site.



May 11, 2017