

Inspection Photos
Location Name: [Nels Christiansen Unit 1]
API: 05-123-07662



Nels Christiansen Unit #1 battery

**Flow line from Christiansen Unit #2 leaking by Kerr Megee
ECD Burner**

