

**Inspection Photos**  
**Location Name: [Nels Christiansen Unit 2]**  
**API: 05-123-08808**



**Nels Christiansen Unit #1 battery**

**Flow line from Christiansen Unit #2 leaking by Kerr Megee  
ECD Burner**