

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2017

Submitted Date:

05/15/2017

Document Number:

674901650**FIELD INSPECTION FORM**

Loc ID 325953 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Gintautas, Peter		peter.gintautas@state.co.us	
Chesson, Bob		robert.chesson@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215628	WELL	PR	03/21/1989	GW	067-07233	WILBOURN FEDERAL 1	EI

General Comment:

On May 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Wilbourn Federal #1. The purpose of this location inspection was to collect samples for the COGCC's statewide produced water NORM study. BP representative Jeramie Price was on site during this inspection. For the most recent field inspection report for this facility, please refer to document #680600075.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near separator. Old style sign remains on location.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing surrounds well head and pump jack.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Sample	Sample Type: PRODUCED
Time: 05/10/2017 10:45 (MM/dd/yyyy hh:mm)	GPS: Lat 37.291934 Long -107.679939
BTEX: _____	TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____
Dissolved Methane: _____	Composition: _____ Stable Isotopes: _____ 8260: _____
8270: _____	RCRA Metals: _____ 910-Metals: _____ PAH: _____
Other: 2017 COGCC Produced Water NORM Study	
Comment: _____	

Sample	Sample Type: PRODUCED
Time: 05/10/2017 11:00 (MM/dd/yyyy hh:mm)	GPS: Lat 37.291934 Long -107.679939
BTEX: _____	TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____
Dissolved Methane: _____	Composition: _____ Stable Isotopes: _____ 8260: _____
8270: _____	RCRA Metals: _____ 910-Metals: _____ PAH: _____
Other: 2017 COGCC Produced Water NORM Study	
Comment: _____	

Lab:

Lab Name _____

ALS Environmental _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass					
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On May 10, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Wilbourn Federal #1. The purpose of this location inspection was to collect samples for the COGCC's statewide produced water NORM study. BP representative Jeramie Price was on site during this inspection. For the most recent field inspection report for this facility, please refer to document #680600075. One produced water sample was collected from the BP Wilbourn Federal #1 at the well head. Another produced water sample was collected from the same valve as a duplicate.	hughesj	05/15/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901651	Wilbourn Federal #1 location photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147723
674901652	1" valve that samples were collected from.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147724
674901653	Piping configuration for sample collection.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147725
674901654	BP representative assisting in sample collection.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147726