

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2017

Submitted Date:

05/15/2017

Document Number:

674200067

**FIELD INSPECTION FORM**

Loc ID 336382 Inspector Name: Gomez, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@crestonepr.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271268	WELL	PR	06/22/2010	GW	123-22015	WOOLLEY 21-7	SI
284163	WELL	PR	08/11/2006	OW	123-23758	BILLINGS 21-7	SI
421621	WELL	PR	09/05/2012	GW	123-32979	WOOLLEY 11-7	SI
421629	WELL	PR	11/05/2012	OW	123-32982	WOOLLEY 22-7	SI
421632	WELL	PR	10/10/2012	OW	123-32984	WOOLLEY 2-4-7	SI
421635	WELL	PR	11/02/2012	OW	123-32986	WOOLLEY 4-0-7	SI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	#		
Comment:	APPROX 20' ,OBILE SOUND WALLS ON SOUTH END OF LOCATION FOR SOUND MITIGATION		
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	APPROX 32' SOUND WALLS ON WEST AND NORTH END OF LOCATION FOR SOUND MITIGATION		
Corrective Action:			Date:

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 271268 Type: WELL API Number: 123-22015 Status: PR Insp. Status: SI

**Complaint**

Comment: [Complaint Received May 15, 2017](#)  
[Field Inspector Assigned: Jason E. Gomez](#)  
[Complaint Received:](#)  
 Date: 5-12-2017/ 5-14-2017 Time 1000 Hrs  
 Contacted by Complaint Specialist per Complaint Response forms  
 Date: 5--2017  
 Well Number#: Location #: 336382  
 Inspection Document #: 674200067  
 Nature of complaint: Noise/Odor  
 Field Inspector Actions:  
 On 5-15-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about noise occurring in the Erie are of CR 10.5 and WCR 3.  
 On 5-15-2017, I performed a complete site inspection of the location located approx. 1/4 mile north of 3 WCR. At the time of inspection, I observed a frac pad where Crestone Peak is conducting remote frac operations on the Woolley Becky Sosa location and the Crestone Peak Morgan Hills locations. I reviewed location records, which did not show any abnormal fracking conditions at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information which also did not show any exceedance of COGCC rules at the times of the complaints.  
 I spoke to Crestone personnel on location and they informed me the Liberty Oil Field Services company was going to be installing directional mufflers on the equipment in an attempt to do additional sound mitigation to the equipment.  
 I also performed sound study at location approx. 350' to the SW of the noise source per COGCC guidance, the study did not show any violation of COGCC rules at the time of the study.  
 All information reviewed and site inspection information were submitted to the complaint specialist for further review.  
 No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Facility ID: 284163 Type: WELL API Number: 123-23758 Status: PR Insp. Status: SI

Facility ID: 421621 Type: WELL API Number: 123-32979 Status: PR Insp. Status: SI

Facility ID: 421629 Type: WELL API Number: 123-32982 Status: PR Insp. Status: SI

Facility ID: 421632 Type: WELL API Number: 123-32984 Status: PR Insp. Status: SI

Facility ID: 421635 Type: WELL API Number: 123-32986 Status: PR Insp. Status: SI

--

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass			Material Handling And Spill Prevention	Pass	
Gravel	Pass			Vehicle Tracking	Pass	
Berms	Pass	Compaction	Pass	Covering Materials	Pass	
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674200068	sound study	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147790">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147790</a>
674200069	PHOTO OF LOCATION OF SOUND STUDY	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147791">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147791</a>