

Photo#1:
Overview of Location.



May 11, 2017

Photo#2:

Ditch, Trap & Drain along North side of Location.

Photo#3:



May 11, 2017

Photo#4:

Ditch along base of Pad at South side of Site.

*



Photo#5:

Series of Trap, Retention Pond down slope from Fill Slope.



May 11, 2017

Photo#6:

Cut Slope along SE side of Site



Photo#7:

Fill slope along NW side of Site.



May 11, 2017

Photo#8:

One of two areas at base of Cut Slope that are eroding and appear to have not been contoured and revegetated.



May 11, 2017