

Photo#1:
Overview of Location to SW.



May 11, 2017

Photo#2:

Slough & Seep area of Cut slope; fencing project in foreground.



May 11, 2017

Photo#3:

View to NE along ditch to Slough area of Cut Slope.



Photo#4:

View to SW along Ditch to Slough area of Cut Slope



May 11, 2017

Photo#5:

Thistle rosettes in Cut Slope area



Photo#6:

Houndstongue rosettes in Cut Slope area



May 11, 2017

Photo#7:
Old growth Thistle on Cut Slope..



May 11, 2017