

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2017

Submitted Date:

05/16/2017

Document Number:

684903755

FIELD INSPECTION FORM

Loc ID 442284 Inspector Name: Pesicka, Conor On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 BROADWAY STE 2300
City: DENVER State: CO Zip: 80290

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442295	WELL	DG	03/14/2017	LO	123-41781	Horsetail 07F-1838	AO
442297	WELL	WO	06/22/2016	LO	123-41783	Horsetail Fed 07F-0639	AO

General Comment:

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:	Sign in at shack		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 442295 Type: WELL API Number: 123-41781 Status: DG Insp. Status: AO

Well Stimulation

Stimulation Company: Halliburton Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) 2838

Bradenhead Psi: _____

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: Just finished, preparing to move to next well

Corrective Action: _____

Date: _____

Facility ID: 442297 Type: WELL API Number: 123-41783 Status: WO Insp. Status: AO

Well Stimulation

Stimulation Company: Halliburton Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: 0

Intermediate: _____

Production: 5000

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: 0

Frac Flow Back: _____

Fluid: _____

Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	
Seeding	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT