

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2017

Submitted Date:

05/16/2017

Document Number:

675103599**FIELD INSPECTION FORM**

Loc ID 335883 Inspector Name: GRANAHAN, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp
Reid, Van		van_reid@xtoenergy.com	Piceance Creek insp
Kardos, Kelly		kelly_kardos@xtoenergy.com	Piceance Creek insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287339	WELL	DG	01/01/2012	GW	103-10921	FREEDOM UNIT 197-31A3	WO

General Comment:[On location to witness MIT - form 42 doc # 401274023](#)

Inspected Facilities									
Facility ID:	287339	Type:	WELL	API Number:	103-10921	Status:	DG	Insp. Status:	WO
Workover									
Comment:	<div>MIT - 4505' surface casing TD with cement plug at bottom - no perfs Psi before test - 0 Starting test psi - 540 5 min - 540 10 min - 540 15 min - 540 No change in pressure</div>								
Corrective Action:								Date:	