

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2017

Submitted Date:

05/16/2017

Document Number:

680301933

FIELD INSPECTION FORM

Loc ID 312252 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 11001
Name of Operator: BROWN OIL & GAS LLC
Address: 10481 COUNTY ROAD 20.5
City: STERLING State: CO Zip: 80751

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Mark	970-522-1072	brown_oil_and_gas@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219926	WELL	PR	01/04/2010	GW	075-08045	HALEY SMITH 1	PR

General Comment:

[Routine Site Inspection FIR](#)

Location			
Lease Road:			
Type	Access		
comment:	Satisfactory		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	PW		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Satisfactory - Crude		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	NG Engine		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Propane tank		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	FIBERGLASS AST		40.911252,-103.345441
Comment:	No problems observed				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.911690,-103.345582
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 219926 Type: WELL API Number: 075-08045 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	425466	200321849	
	425466	200321849	