

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2017

Submitted Date:

05/10/2017

Document Number:

684903738**FIELD INSPECTION FORM**

Loc ID 448376 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448373	WELL	DG	03/15/2017		123-43873	Wells Ranch State AA33-750	AO
448374	WELL	DG	03/10/2017		123-43874	Wells Ranch State AA33-755	AO
448381	WELL	DG	03/04/2017		123-43878	Wells Ranch State AA33-744	AO

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Sign in at shack		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:  Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 448373 Type: WELL API Number: 123-43873 Status: DG Insp. Status: AO**Well Stimulation**Stimulation Company: Halliburton Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: 0

Intermediate: \_\_\_\_\_

Production: 3800Instantaneous Shut-In Pressure (ISIP) 3800Bradenhead Psi: 0

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: Changing ops

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 448374 Type: WELL API Number: 123-43874 Status: DG Insp. Status: AO**Well Stimulation**Stimulation Company: Halliburton Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**Maximum Casing Recorded: 7200 PSI

Tubing: \_\_\_\_\_

Surface: 0

Intermediate: \_\_\_\_\_

Production: 3800Instantaneous Shut-In Pressure (ISIP) 3800Bradenhead Psi: 0

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: Changing ops

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 448381 Type: WELL API Number: 123-43878 Status: DG Insp. Status: AO**Well Stimulation**Stimulation Company: Halliburton Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: 0

Intermediate: \_\_\_\_\_

Production: 3800Instantaneous Shut-In Pressure (ISIP) 3800Bradenhead Psi: 0

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	
Berms	Pass					
Seeding	Pass					
Waddles	Pass					

Comment: [Ongoing precipitation event](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401279783	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143867">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143867</a>